BALLUFF



BVS ID

FW 1.0.3

OVERVIEW

SensorApp FW-Version	**1.0.3**
CREATION DATE	November 29th, 2022
PRODUCTS	BVS ID-M1280BF1-L3-000 BVS ID-M1280CF1-L3-000
PREVIOUS REVISION	None
MVTEC HALCON LIBRARY VERSION USED:	22.05.0

NEW TOOLS / TOOL FUNCTIONS

Initial version

BUG FIXES

- None

KNOWN FUNCTION RESTRICTIONS

- The status LED display does not reflect the correct system status.
- Reset to factory settings via Balluff Engineering Tool (BET) is disabled.
- Upload of image files does not work properly for Chromium-based browsers.
  Workaround: Use image file upload facilities via the Samba shared folder.
- IO-Link CCM Variant is not supported yet. If the device was accidentally set to the CCM Variant, it can be changed back by setting ISDU 85 subindex 0 to 1.

COMPATIBILITY TO PREVIOUS VERSIONS / HINTS

- None

HOW TO INSTALL

- Download and unzip the files from our home page in the designated product section.

IdentSensor BVS ID:

- Open the update folder with the Windows file explorer of your (running) SmartCamera (e.g. **\\192.168.10.2\updates**) - (eventually use once Login: **expert** Password: **expert**)
- Copy the firmware file e.g. **BVSID_FW_1.0.3.xx.yyyy.zzz.sh** (~200MB) into this folder
- After ~3min the controller reboots automatically and the browser automatically updates. In case there is no automatic refresh please restart your browser.
- Please verify the “Firmware Version” in the SensorApp.
- The updated hardware and software manuals are available through the online help section

ADDITIONAL SUPPORT

Headquarter & Technical Service Hub EMEA	**Technical Service Hub APAC**	**Technical Service Hub AMAS**
Balluff GmbH Schurwaldstraße 9 73765 Neuhausen a.d.F. Germany www.balluff.com/go/support	Balluff Automation (Shanghai) Co., Ltd. No. 800 Chengshan Rd, 8F, Buidling A, Yunding International Commercial Plaza 200125, Pudong, Shanghai Greater China www.balluff.com/go/support	Balluff Inc. 8125 Holton Drive Florenxe, KY 41042 USA www.balluff.com/go/support