

# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20180530-E475523  
**Report Reference** E475523-20150508  
**Issue Date** 2018-MAY-30

**Issued to:** BALLUFF GMBH  
SCHURWALDSTR 9  
NEUHAUSEN, 73765  
Germany

**This is to certify that representative samples of** EMERGENCY STOP DEVICES  
See addendum for models.

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

**Standard(s) for Safety:** UL 61496-1 - Electro-Sensitive Protective Equipment, Part 1: General Requirements and Tests  
UL 61496-2 - Electro-Sensitive Protective Equipment, Part 2: Particular Requirements for Equipment Using Active Opto-Electronic Protective Devices (AOPDs)  
CSA C22.2 NO. 14 - Industrial Control Equipment

**Additional Information:** See the UL Online Certifications Directory at [www.ul.com/database](http://www.ul.com/database) for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20180530-E475523  
**Report Reference** E475523-20150508  
**Issue Date** 2018-MAY-30

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Type 2 or Type 4 Light curtain:

BLG4A-015-600-014-O01-SX, BLG4A-030-600-014-O01-SX, BLG4A-045-600-014-O01-SX,  
BLG4A-060-600-014-O01-SX, BLG4A-075-600-014-O01-SX, BLG4A-090-600-014-O01-SX,  
BLG4A-105-600-014-O01-SX, BLG4A-120-600-014-O01-SX, BLG4A-135-600-014-O01-SX,  
BLG4A-150-600-014-O01-SX, BLG4A-165-600-014-O01-SX, BLG4A-180-600-014-O01-SX,  
BLG4A-015-19X-030-O01-SX, BLG4A-030-19X-030-O01-SX, BLG4A-045-19X-030-O01-SX,  
BLG4A-060-19X-030-O01-SX, BLG4A-075-19X-030-O01-SX, BLG4A-090-19X-030-O01-SX,  
BLG4A-105-19X-030-O01-SX, BLG4A-120-19X-030-O01-SX, BLG4A-135-19X-030-O01-SX,  
BLG4A-150-19X-030-O01-SX, BLG4A-165-19X-030-O01-SX, BLG4A-180-19X-030-O01-SX,  
BLG4A-050-50X-B02-O01-SX, BLG4A-080-50X-B03-O01-SX, BLG4A-090-50X-B04-O01-SX,  
BLG4A-120-50X-B04-O01-SX



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

